Manhole Inspection Report



Date: 05/14/2018 Weather: Coding: RZMACP

 MH#:
 M-504-054
 Owner:
 NA
 Len. Surveyed:
 7.6

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 8.3

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: South of Old Ridge Rd. 162' East of Project: Hobart, IN
City: Hobart, IN GPS Northing: 41.53908157

City: Hobart, IN GPS Northing: 41.53908157
Location: GPS Easting: -87.27650452

Drain Area: West GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	1.50	O&M Quick:	2111	O&M Rating:	3.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	1.50	Overall Quick:	2111	Overall Rating:	3.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
1-504-05	54				
	√ .0	MGP	General Photo	10	NA
ш	.7	RFJ	Roots Fine Joint	23	M 1
	6.1	DSF	Deposits Settled Fine	45	M 2
ш	7.6	MGO	General Observation	60	NA
Camera Direction					

Code:



Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACCESS MH**

MGP

General Photo

2

Wednesday, May 3, 2023



Code: RFJ

Description: Roots Fine Joint

Distance (ft): .7
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 5
Clock To: 8
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 6.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:



Code: MGO

Description: General Observation

Distance (ft): 7.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023