## **Manhole Inspection Report**



Date:

05/14/2018

Weather:

Coding: **RZMACP** 

MH#: P.O.#:

M-504-067

Owner: NA Len. Surveyed:

11.0 Rim to Invert: 11.4

Customer:

Surveyor: Jen Costello U-907-5518 Cert. #:

Concrete Wall Material:

(reinforced)

Street:

Wisconsin St. 167' North of Ridge Rd Project:

Hobart, IN

City:

**GPS Northing:** 

2901798.043

Location:

GPS Easting:

2901798.043

None

Drain Area: Cover Shape: Northwest

Hobart, IN

GPS Accuracy: **Sub-Meter** 

Cover Size:

Circular

22.5

Evidence of Surcharge: No

2100

3100

3121

Potential for Runoff:

Comments:

O&M Index:

2.00 3.00

O&M Quick: Structural Quick:

O&M Rating:

Structural Rating: Overall Rating:

2.00 3.00 5.00

Structural Index: Overall Index:

2.50 Overall Quick:

Wednesday, May 3, 2023

1

0 MG 0 DAI 9 DB 1.0 MG	E D	General Photo Deposits Attacher Displaced Brick General Observat		10 21 34 66	NA M 2 S 3 NA
D DAI	E D	Deposits Attached Displaced Brick		21	M 2 S 3
9 DB		Displaced Brick		34	S 3
			tion		
1.0 MG	5O G	General Observat	tion	66	NA
	1	•			



Description:	<b>General Photo</b>
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent:	NO.
Step: Remarks:	NO access mh

MGP

Wednesday, May 3, 2023

Code:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks:




Code: DB

Description: Displaced Brick

Distance (ft): .9
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 3
Clock To: 4
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 11.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey

Wednesday, May 3, 2023