## **Manhole Inspection Report**



Date: 05/15/2018 Weather: Coding: RZMACP

 MH#:
 M-504-101
 Owner:
 NA
 Len. Surveyed:
 7.0

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 7.5

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: **367' North of Ridge Rd. 201' East of** Project: **Hobart, IN** 

City: Hobart, IN GPS Northing: 41.54092789
Location: GPS Easting: -87.27256012

Drain Area: Northwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-504-10	)1				
$\overline{}$	0	MGO	General Observation	10	NA
- 11	7.0	MGO	General Observation	36	NA
Camera Direction					



Code: MGO
Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: MGO

Description: General Observation

Distance (ft): 7.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY