Manhole Inspection Report



Date: 04/11/2018 Weather: Coding: RZMACP

 MH#:
 M-504-125
 Owner:
 NA
 Len. Surveyed:
 3.9

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 4.5

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 41st Ave. 162' East of Guyer St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 2899864.535

Location: GPS Easting: **2899864.535**

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: Yes


Cover Size: 23.0 Potential for Runoff: None

Comments:

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
504-125				
.0	MGP	General Photo	10	NA
2.1	MGO	General Observation	26	NA
2.1	MGP	General Photo	39	NA
3.3	MGO	General Observation	55	NA
H				




Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGO


Description: General Observation

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Surcharge



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 3.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.