Date:	04/28/2018	Weather:		Coding:	RZMACP
MH#:	M-505-077	Owner:	NA	Len. Surveyed:	4.5
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	5.1
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	4th Pl. to the West.		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2900656.35	
Location:			GPS Easting:	2900656.35	
Drain Area:	West		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	3.00	Structural Qu	iick: 3100	Structural Rating:	3.00
Overall Index:	3.00	Overall Quick	с: <mark>3100</mark>	Overall Rating:	3.00

Position	n Code	Observation	Video (sec)	Grade
M-505-077				
.0	MGO	General Observation	10	NA
1.3	MGO	General Observation	26	NA
4.5	SAV	Surface Aggregate Visible	46	S 3
4.5	MGO	General Observation	57	NA
Camera Direction				



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	access MH



Code:	MGO
Description:	General Observation
Distance (ft):	1.3
	1.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME



Code:	SAV
Description:	Surface Aggregate Visible
Distance (ft):	4.5
Structural Grade:	3
Structural Grade.	5
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft):	4.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY