Date:	04/24/2018	Weather:		Coding:	RZMACP
MH#:	M-506-010	Owner:	NA	Len. Surveyed:	11.8
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	13.1
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Colorado St. 123' N	orth of 8th St.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2900551.79	
Location:			GPS Easting:	2900551.79	
Drain Area:	Southwest		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qu	uick: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quic	k: 3121	Overall Rating:	5.00

	Position	Code	Observation	Video (sec)	Grade
506-010					
	.0	MGO	General Observation	10	NA
	.0	DB	Displaced Brick	21	S 3
	2.1	MGO	General Observation	39	NA
	11.8	OBM	Obstacle Pipe Material	71	M 2
	11.8	MGO	General Observation	83	NA



MGO General Observation
.0
0
0
NO
ACCESS MH



Code: DB Description: Displaced Brick Distance (ft): .0 Structural Grade: 3

O&M Grade:	0
Clock Start/From:	8
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step:	2.1 0 0
Remarks:	UNDERSIDE OF FRAME



Code: Description:	OBM Obstacle Pipe Material
Distance (ft):	11.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	3
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code: Description: MGO General Observation

Distance (ft):	11.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY