## **Manhole Inspection Report**



Date:

Customer:

04/27/2018

Weather:

Cert. #:

Coding: **RZMACP** 

MH#:

M-506-020

Owner: NA Len. Surveyed:

10.8

P.O.#:

Surveyor:

Jen Costello

Rim to Invert:

11.3 Concrete Wall Material:

(reinforced)

Street:

North of 7th Pl. West of Wisconsin S Project:

Hobart, IN

City:

**GPS Northing:** 

U-907-5518

2901702.014

Location:

GPS Easting:

2901702.014

Drain Area:

GPS Accuracy:

**Sub-Meter** 

Cover Shape:

Southwest Circular

Hobart, IN

Evidence of Surcharge: No

Cover Size: Comments: 22.5

Potential for Runoff:

None

O&M Index:

2.00 O&M Quick: 4.00

Structural Quick:

2200

O&M Rating:

Structural Rating: Overall Rating:

4.00 4.00

8.00

Structural Index: Overall Index:

2.67 Overall Quick:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
06-020				
.0	MGO	General Observation	10	NA
0.	FM	Fracture Multiple	20	S 4
1.4	MGP	General Photo	36	NA
2.2	IW	Infil Weeper	51	M 2
8.2	OBR	Obstacle Rocks	75	M 2
10.8	MGO	General Observation	91	NA



Code: MGO
Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: ACCESS MH



Code: FM

Description: Fracture Multiple

Distance (ft): .0
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 1.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 1
1st Value:
2nd Value:

Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023



Code: OBR

Description: Obstacle Rocks

Distance (ft): 8.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 10.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY