Manhole Inspection Report



04/24/2018 Date:

M-506-038

Weather:

Coding:

RZMACP

6.6

6.8

MH#:

Owner: NA

Len. Surveyed: Rim to Invert:

P.O.#:

John Kuglmaier Surveyor: U-1215-07002349 Cert. #:

Wall Material:

Concrete (reinforced)

Street: City:

Customer:

273' West of 10th St. and Decatur St Project:

GPS Northing:

Hobart, IN 2899832.703

Location:

2899832.703

Drain Area:

GPS Easting:

Cover Shape:

Southwest

Hobart, IN

GPS Accuracy:

Sub-Meter

Cover Size:

Circular 22.5

Evidence of Surcharge: No

Potential for Runoff: None

2100

Comments:

O&M Index: Structural Index:

Overall Index:

2.00 0.00

2.00

O&M Quick:

Structural Quick: Overall Quick:

2100 0000

O&M Rating: Structural Rating: Overall Rating:

2.00 0.00 2.00

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
M-506-038				
.0	MGP	General Photo	10	NA
1.1	IS	Infil Stain	24	NA
2.3	MGP	General Photo	40	NA
2.9	DSF	Deposits Settled Fine	54	M 2
5.8	MGO	General Observation	72	NA
Camera Direction				


Code:



Description:	General Photo
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: IS

Description: Infil Stain

Distance (ft): 1.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9
Clock To: 11

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 2.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 5.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 4