Manhole Inspection Report



Date: 04/07/2018 Weather: Coding: RZMACP

MH#: M-507-025 Owner: NA Len. Surveyed: 6.5
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 7.0

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: West of Colorado St. 473' North of C Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0**

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 22.5 Potential for Runoff: None
Comments: THIS MANHOLE HAS NO COVER. REPORTED TO PUBLIC WORKS

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0000 0.00 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

.0 MGP General Photo 10 NA 2.3 MGP General Photo 28 NA 3.4 DAZ Deposits Attached Other 44 M 2 6.0 MGO General Observation 61 NA
.0 MGP General Photo 10 NA 2.3 MGP General Photo 28 NA 3.4 DAZ Deposits Attached Other 44 M 2 6.0 MGO General Observation 61 NA
3.4 DAZ Deposits Attached Other 44 M 2 6.0 MGO General Observation 61 NA
6.0 MGO General Observation 61 NA



General Photo
.0
0
0
NO

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value:

Value Percent:

Step: NO

Remarks:

2nd Value:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 3.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 6.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3