Manhole Inspection Report

	spection kepoi	-			ROBOTIC
Date:	04/26/2018	Weather:		Coding:	RZMACP
MH#:	M-507-027	Owner:	NA	Len. Surveyed:	7.5
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	7.8
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	West of Colorado S	St. 164' South of 1	Project:	Hobart, IN	
City:	Hobart, IN	(GPS Northing:	2900629.828	
Location:		C	GPS Easting:	2900629.828	
Drain Area:	Southwest	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	E	vidence of Surcharge:	No	
Cover Size:	22.5	F	Potential for Runoff:	None	
Comments:					
O&M Index:	2.00	O&M Quick:	2200	O&M Rating:	4.00
Structural Index:	0.00	Structural Quic	ck: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2200	Overall Rating:	4.00

RedZone

Position	Code	Observation	Video (sec)	Grade
л- 507-0 27				
.0	MGO	General Observation	10	NA
1.6	MGP	General Photo	27	NA
5.5	DSF	Deposits Settled Fine	48	M 2
7.4	OBR	Obstacle Rocks	63	M 2
7.5	MGO	General Observation	75	NA
Camera Direction				



MGO General Observation
.0
0
0
NO
ACCESS MH



Code:	MGP General Photo
Description:	General Photo
Distance (ft):	1.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME

DSF



Description:	Deposits Settled Fine	
Distance (ft):	5.5	
Structural Grade:	0	
O&M Grade:	2	
Clock Start/From:	12	
Clock To:	12	
1st Value:		
2nd Value:		
Value Percent:	5.000	
Step:	NO	
Remarks:		

Code:



OBR Obstacle Rocks
7.4
0
2
5
7
10.000
NO



Code:	MGO
Description:	General Observation
Distance (ft):	7.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY