## **Manhole Inspection Report**



Date: 03

03/28/2018

Weather:

Cert. #:

NA

Coding:

**RZMACP** 

MH#:

M-507-044

Owner: N

Len. Surveyed:

P.O.#:

Surveyor: John Kuglmaier

Rim to Invert:

Wall Material: Concrete

(reinforced)

5.6

6.5

Street:

Customer:

**Delaware St. 380' Northeast of Csok** Project:

Hobart, IN

City: Location: Hobart, IN

GPS Northing:

0.0

\_

GPS Easting:

0.0

Drain Area: Cover Shape: Southwest

GPS Accuracy:

**Nearest Meter** 

Cover Size:

Circular

Evidence of Surcharge:

U-1215-07002349

Yes

Cover size.

ver Size: **22.5** 

Potential for Runoff:

None

O&M Index:

Structural Index:

Overall Index:

0.00

O&M Quick:
Structural Quick:

Overall Quick:

0000


0000

\_O&M Rating: \_Structural Rating: Overall Rating: 0.00 0.00 0.00

Wednesday, May 3, 2023


1

Position	Code	Observation	Video (sec)	Grade
M-507-044				
.0	MGP	General Photo	10	NA
2.2	MGP	General Photo	28	NA
3.2	MGO	General Observation	44	NA
4.3	MGO	General Observation	58	NA
Camera Direction				



Code:	MGP
Description:	<b>General Photo</b>
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

2 Wednesday, May 3, 2023



Code: MGP

Description: General Photo


Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO


Description: General Observation

Distance (ft): 3.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: Surcharge



Code: MGO

Description: General Observation

Distance (ft): 4.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock StartyFfor Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.