Manhole Ins	spection Repor	t			RedZo
Date:	03/28/2018	Weather:		Coding:	RZMACP
MH#:	M-507-045	Owner:	NA	Len. Surveyed:	3.5
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	3.9
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	13th Pl. 315' East of Virginia St. Project:		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southwest		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
Structural Index:	0.00	Structural Qui	ick: 0000	Structural Rating:	0.00
Overall Index:	3.00	Overall Quick		Overall Rating:	3.00

Position	Code	Observation	Video (sec)	Grade
л- 507-0 45				
0.	MGP	General Photo	10	NA
.1	DSF	Deposits Settled Fine	22	M 3
1.4	MGP	General Photo	38	NA
2.9	MGO	General Observation	54	NA
Camera Direction				




Code:	MGP
Description:	General Photo
	-
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:DSFDescription:Deposits Settled Fine

Distance (ft):	.1
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	15.000
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft):	1.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft):	2.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.