Manhole Inspection Report



Date: 03/28/2018 Weather: Coding: RZMACP

 MH#:
 M-507-065
 Owner:
 NA
 Len. Surveyed:
 7.4

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 7.9

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: Csokasy Ln. 179' East of Virginia St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-507-06	5				
$\overline{}$.0	MGP	General Photo	10	NA
- 11	1.6	IS	Infil Stain	25	NA
- 11	2.6	MGP	General Photo	40	NA
	4.2	DSF	Deposits Settled Fine	57	M 2
	6.1	MGO	General Observation	72	NA
Camera Direction					

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023



Code: IS


Description: Infil Stain

Distance (ft): 1.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10
Clock To: 5
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 4.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 6.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023