## **Manhole Inspection Report**



Date: 04/24/2018 Weather: Coding: RZMACP

MH#: M-507-074 Owner: NA Len. Surveyed: 5.0
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 5.9

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 11th St. Colorado St. to the Northea Project: Hobart, IN

City: Hobart, IN GPS Northing: 2900832.61 Location: GPS Easting: 2900832.61

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

3.00 3100 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 3.00 3100 3.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Posit	ion Code	Observation	Video (sec)	Grade
л-507-074				
.0	MGP	General Photo	10	NA
2.2	DSF	Deposits Settled Fine	26	M 3
2.4	MGP	General Photo	40	NA
4.4	MGO	General Observation	58	NA
Camera Direction				




Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023

Code:



Code: DSF

Description: Deposits Settled Fine

Distance (ft): 2.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 15.000 Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

2nd Value: Value Percent:

Step: NO

Remarks:

1st Value:



Code: MGO

Description: General Observation

Distance (ft): 4.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3