Date:	04/04/2018	Weather:		Coding:	RZMACP
MH#:	M-507-091	Owner:	NA	Len. Surveyed:	4.1
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	4.8
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	On Wisconsin St. 3	71' North of 14th	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southwest		GPS Accuracy:	Nearest Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Qu	lick: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	c: 0000	Overall Rating:	0.00

Position	Code	Observation	Video (sec)	Grade
л-507-091				
.0	MGP	General Photo	10	NA
1.9	IS	Infil Stain	26	NA
2.1	MGP	General Photo	40	NA
3.5	MGO	General Observation	57	NA
Camera Direction				



Code:	MGP
Description:	General Photo
/0.	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	IS
Description:	Infil Stain
Distance (ft):	1.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft):	2.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft):	3.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.