Manhole Inspection Report



Date: 04/11/2018 Weather: Coding: RZMACP

MH#: M-603-002 Owner: NA Len. Surveyed: 4.7
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.4

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: South of 39th Pl. in Apartment Com Project: Hobart, IN

City: Hobart, IN GPS Northing: 2902960.41 Location: GPS Easting: 2902960.41

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: Yes
Cover Size: 23.0 Potential for Runoff: None

Comments:

3.00 3100 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 3.00 3100 3.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
м-603-002				
.0	MGP	General Photo	10	NA
1.6	MGP	General Photo	27	NA
1.9	DAZ	Deposits Attached Other	41	M 3
3.9	MGO	General Observation	57	NA
Camera Direction				

Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: NO Step: Remarks:

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 1.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 15.000
Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 3.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/Pro Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3