
Date:	04/11/2018	Weather:		Coding:	RZMACP
MH#:	M-603-007	Owner:	NA	Len. Surveyed:	8.5
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	10.0
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	40th Place 185' East of Wisconsin St. Project:		Hobart, IN		
City:	Hobart, IN		GPS Northing:	2901971.251	
Location:		(GPS Easting:	2901971.251	
Drain Area:	Northwest	(GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular	E	Evidence of Surcharge:	No	
Cover Size: Comments:	23.0	F	Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quid	ck: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Position	Code	Observation	Video (sec)	Grade
-603-007				
.0	MGP	General Photo	10	NA
2.2	MGP	General Photo	28	NA
/5.1	IS	Infil Stain	47	NA
6.7	DSF	Deposits Settled Fine	62	M 2
7.5	MGO	General Observation	75	NA
μ.				



Code: Description:	MGP General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code:	MGP
Description:	General Photo
Distance (ft):	2.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	IS Infil Stain
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	5.1 0 0 12 12
Step: Remarks:	NO



Code:	DSF
Description:	Deposits Settled Fine
//	
Distance (ft):	6.7
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code:MGODescription:General Observation

Distance (ft):7.5Structural Grade:0O&M Grade:0Clock Start/From:Clock To:-1st Value:-2nd Value:-Value Percent:-Step:NORemarks:Ins. Comp.