## **Manhole Inspection Report**



Date: 04/08/2018 Weather: Coding: RZMACP

MH#: M-603-036 Owner: NA Len. Surveyed: 2.8
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 4.0

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: South of Hwy 6. 327' East of Wiscon Project: Hobart, IN

City: Hobart, IN GPS Northing: 2902077.467

Location: GPS Easting: 2902077.467

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None

Comments:

3.00 3100 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 3.00 3100 3.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Po	osition	Code	Observation	Video (sec)	Grade
M-603-036					
.0		MGP	General Photo	10	NA
1.2	2	DSF	Deposits Settled Fine	24	M 3
1.2	2	MGP	General Photo	38	NA
2.4	4	MGO	General Observation	54	NA
Camera Direction					

Code:



Description:	<b>General Photo</b>		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:			

MGP

Wednesday, May 3, 2023 2



Code: DSF

Description: Deposits Settled Fine

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Value Percent: **15.000** Step: **NO** 

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 2.4
Structural Grade: 0

O&M Grade: **0** 

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023