## **Manhole Inspection Report**



Date:

05/01/2018

Weather:

Cert. #:

Coding: **RZMACP** 

MH#:

M-604-003

Owner: NA Len. Surveyed:

P.O.#:

Surveyor: Jen Costello Rim to Invert:

5.6 Wall Material: **Concrete** 

(reinforced)

5.0

Customer:

Cleveland Ave. 175' West of Beverly Project:

Hobart, IN

Street: City:

Hobart, IN

**GPS Northing:** 

U-907-5518

41.5362854

Location:

GPS Easting:

-87.26144409

Drain Area:

West

GPS Accuracy:

**Nearest Meter** 

Cover Shape: Cover Size:

Circular

Evidence of Surcharge: No

22.5

Potential for Runoff: None

2100

Comments:

O&M Index:

0.00 2.00

O&M Quick: Structural Quick:

0000 O&M Rating: 2100

0.00 2.00

2.00


Structural Index: Overall Index:

2.00 Overall Quick: Structural Rating: Overall Rating:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
M- <del>604-0</del> 03				
.0	CL	Crack Longitudinal	10	S 2
1.2	MGO	General Observation	26	NA
5.0	MGO	General Observation	46	NA
Camera Direction				



Description: **Crack Longitudinal** Distance (ft): .0 Structural Grade: 2 O&M Grade: 0 Clock Start/From: 9 Clock To: 1st Value: 2nd Value: Value Percent: NO Step:

 $\mathsf{CL}$ 

Wednesday, May 3, 2023 2

Code:

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 5.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3