Manhole Inspection Report



Date: 04/29/2018 Weather: Coding: RZMACP

 MH#:
 M-604-008
 Owner:
 NA
 Len. Surveyed:
 8.0

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 8.1

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: Intersection of Beverly Blvd. and Wil Project: Hobart, IN

City: Hobart, IN GPS Northing: 2903789.813

Location: GPS Easting: 2903789.813
Drain Area: West GPS Accuracy: Sub-Meter

Drain Area: West GPS Accuracy: Sub-No Cover Shape: Circular Evidence of Surcharge: No

Cover Size: 22.5 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Pos	ition Code	Observation	Video (sec)	Grade
M-604-008				
.0	MGO	General Observation	10	NA
2.0	MGO	General Observation	28	NA
6.2	DSF	Deposits Settled Fine	50	M 2
8.0	MGO	General Observation	64	NA
Camera Direction				



Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:

MGO

NO

General Observation


Value Percent: Step:

Code:

Description:

Remarks: ACCESS MH

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 6.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): **8.0**Structural Grade: **0**

O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023