Manhole Inspection Report



Date:

05/13/2018

Weather:

Coding:

RZMACP

MH#:

M-604-052

Owner: NA Len. Surveyed: 6.9

P.O.#:

Surveyor: Jen Costello Rim to Invert:

Customer:

U-907-5518 Cert. #:

Wall Material:

Concrete (reinforced)

Street: City:

195' East of Connecticut St. 420' Nor Project:

Hobart, IN

GPS Northing:

2902928.595

Location:

GPS Easting:

2902928.595

Drain Area:

GPS Accuracy:

Sub-Meter

Cover Shape:

Northwest Circular

Hobart, IN

Evidence of Surcharge: No

Cover Size:

22.5

Potential for Runoff: None

Comments:

O&M Index:

0.00

2.00 O&M Quick: Structural Quick:

2100 0000 2100

O&M Rating: Structural Rating:

Overall Rating:

2.00 0.00 2.00

Structural Index: Overall Index:

2.00 Overall Quick:


Wednesday, May 3, 2023

1

л-604-052			Observation	Video (sec)	Grade
/ . /	0	MGP	General Photo	10	NA
1	L.4	MGO	General Observation	26	NA
$/\epsilon$	5.9	MGO	General Observation	50	NA
	5.9	OBB	Obstacle Brick	60	M 2
- 11					
- 11					
- 11					
8					
몇					
Camera Direction					
ը					
اااة					
Ča Ca					
- 111					
	_				

Code:

Description:



Distance (ft):	.0			
Structural Grade:	0			
O&M Grade:	0			
Clock Start/From:				
Clock To:				
1st Value:				
2nd Value:				
Value Percent:				
Step:	NO			
Remarks:	ACCESS MH			

MGP

General Photo

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 1.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 6.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY



Code: OBB

Description: Obstacle Brick

Distance (ft): 6.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6
Clock To:

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023