## **Manhole Inspection Report**



Date: 04/29/2018 Weather: Coding: RZMACP

 MH#:
 M-604-065
 Owner:
 NA
 Len. Surveyed:
 3.0

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 3.0

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: **Beverly Ln. 115' South of Cleveland** Project: **Hobart, IN** 

 City:
 Hobart, IN
 GPS Northing:
 41.53690338

 Location:
 GPS Easting:
 -87.26696014

Drain Area: West GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 24.0 Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-604-065				
.0	MGP	General Photo	10	NA
.9	DSC	Deposits Settled Compacted	23	M 2
1.2	MGO	General Observation	37	NA
3.0	MGO	General Observation	54	NA
Camera Direction				

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023 2



Code: DSC

Description: Deposits Settled Compacted

Distance (ft): .9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 10.000 Step: NO

Remarks:



Code: MGO


Description: General Observation

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 3.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023