## **Manhole Inspection Report**



Date: 04/29/2018 Weather: Coding: RZMACP

MH#:M-604-070Owner:NALen. Surveyed:7.4P.O.#:Surveyor:Jen CostelloRim to Invert:8.3Customer:Cert. #:U-907-5518Wall Material:Brick

Street: Intersection of 1st St. and Washingt Project: Hobart, IN

City: Hobart, IN GPS Northing: 2902125.871
Location: GPS Easting: 2902125.871

Drain Area: West GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
-604-070				
.0	MGO	General Observation	10	NA
1.3	MGO	General Observation	26	NA
6.2	OBR	Obstacle Rocks	49	M 2
6.2	MGP	General Photo	60	NA
7.4	MGO	General Observation	74	NA




Description: **General Observation** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: access mh

MGO

Wednesday, May 3, 2023 2

Code:



Code: MGO

Description: General Observation

Distance (ft): 1.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: OBR

Description: Obstacle Rocks

Distance (ft): 6.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Value Percent: 10.000
Step: NO

Remarks:

Code:

MGP

Description: General Photo



Wednesday, May 3, 2023

Distance (ft): 6.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:

3



Code: MGO

Description: General Observation

Distance (ft): 7.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey

4