## **Manhole Inspection Report**



Date:

05/13/2018

Weather:

NA

Coding:

**RZMACP** 

MH#:

M-604-086

Owner:

Jen Costello

Len. Surveyed: 10.9 11.3 Rim to Invert:

P.O.#:

Customer:

Surveyor: U-907-5518 Cert. #:

Wall Material:

Concrete (reinforced)

Street: City:

Washington St. 273' North of Ridge

Project:

Hobart, IN 2902108.047

Location:

**GPS Northing:** 

GPS Easting:

2902108.047

Drain Area: Cover Shape: Northwest Circular

Hobart, IN

GPS Accuracy: **Sub-Meter** Evidence of Surcharge:

No

Cover Size:

22.5

Potential for Runoff:

None

Comments:

O&M Index:

0.00 O&M Quick:

0000 3100

3100

O&M Rating:

0.00 3.00

3.00

Structural Index: Overall Index:

3.00 Structural Quick: 3.00 Overall Quick:

Structural Rating: Overall Rating:

Wednesday, May 3, 2023

_	Code	Observation	Video (sec)	Grade
4-086				
.0	MGP	General Photo	10	NA
0.	FL	Fracture Longitudinal	22	S 3
1.4	IS	Infil Stain	36	NA
1.4	MGO	General Observation	49	NA
10.9	MGO	General Observation	82	NA



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	access MH	

MGP

Wednesday, May 3, 2023

Code:



Code: FL

Description: Fracture Longitudinal

Distance (ft): .0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 6

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 10.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY