## **Manhole Inspection Report**



Date:

05/13/2018

Weather:

Coding:

**RZMACP** 

(reinforced)

MH#:

M-604-087

Owner: NA

Len. Surveyed: 12.1 11.8

P.O.#:

Surveyor: Cert. #:

Rim to Invert: Jen Costello

Concrete Wall Material:

Street:

Customer:

86' East of Washington 190' North of Project:

Hobart, IN

City:

**GPS Northing:** 

U-907-5518

2902211.718

Location:

GPS Easting:

2902211.718

Drain Area: Cover Shape: Northwest

Hobart, IN

GPS Accuracy:

**Sub-Meter** 

Cover Size:

Circular

22.5

Evidence of Surcharge: No

Comments:

Potential for Runoff:

None

O&M Index: Structural Index:

2.00 0.00

O&M Quick: Structural Quick:

2100 0000

2100

O&M Rating: Structural Rating:

2.00 0.00 2.00

Overall Index:

2.00 Overall Quick: Overall Rating:

Wednesday, May 3, 2023

1

	Position	Code	Observation	Video (sec)	Grade
1-604-08	37				
$\longrightarrow$	0	MGP	General Photo	10	NA
- 11	1.2	MGO	General Observation	26	NA
	8.0	IW	Infil Weeper	52	M 2
ш	12.1	MGO	General Observation	72	NA
Ш					

Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 8.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 12.1

Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023