Manhole Ins	spection Repor	rt			RedZo
Date:	05/13/2018	Weather:		Coding:	RZMACP
MH#:	M-604-088	Owner:	NA	Len. Surveyed:	11.5
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	11.9
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	Pennsylvania St. 188' North of Ridge		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2902344.778	
Location:			GPS Easting:	2902344.778	
Drain Area:	Northwest		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size:	22.5		Potential for Runoff:	None	
Comments:					
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	4.00	Structural Qu	ick: 4100	Structural Rating:	4.00
Overall Index:	3.00	Overall Quick	4121	Overall Rating:	6.00

	Position	Code	Observation	Video (sec)	Grade
604-08	88				
Ÿ	.0	MGP	General Photo	10	NA
	.0	FM	Fracture Multiple	22	S 4
	1.3	MGO	General Observation	38	NA
	8.8	IW	Infil Weeper	66	M 2
ш.	11.5	MGO	General Observation	83	NA
ш.					



Code:	MGP
Description:	General Photo
	•
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:	FM
Description:	Fracture Multiple
	-
Distance (ft):	.0
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	9
Clock To:	1
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGO General Observation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	1.3 0 0 NO UNDERSIDE OF FRAME



IW Infil Weeper
8.8
0
2
10
NO



Code: MGO ervation 1st Value: 2nd Value: Value Percent:

NO

END SURVEY

Wednesday, May 3, 2023

Description:	General Obse
Distance (ft):	11.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	

Step:

Remarks: