Manhole Inspection Report



Date:

05/13/2018

Weather:

Cert. #:

Coding:

RZMACP

8.4

MH#:

M-604-092

Owner: NA Len. Surveyed:

P.O.#:

Surveyor: Jen Costello Rim to Invert:

Concrete Wall Material:

(reinforced)

Street:

Customer:

193' East of Pennsylvania 745' North Project:

Hobart, IN

City:

Hobart, IN

2902542.866

Location:

GPS Northing: GPS Easting:

U-907-5518

2902542.866

Drain Area:

Cover Shape: Cover Size:

Northwest Circular

22.5

GPS Accuracy: **Sub-Meter**

Evidence of Surcharge: No Potential for Runoff: None

Comments:

O&M Index:

2.00 O&M Quick:

2100 O&M Rating:

2.00 0.00

2.00

Structural Index:

0.00 Structural Quick:

0000 Structural Rating: Overall Rating:

2.00 2100 Overall Index: Overall Quick:

Wednesday, May 3, 2023 1

	Position	Code	Observation	Video (sec)	Grade
M-604-092					
	.0	MGP	General Photo	10	NA
	.0	ISSRH	Intruding Sealing Ring Hanging	22	M 2
- 11	1.3	MGO	General Observation	38	NA
	8.4	MGO	General Observation	65	NA
Camera Direction					

Code:



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:	ACCESS MH	

MGP

Wednesday, May 3, 2023



Code: ISSRH

Description: Intruding Sealing Ring Hanging

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 3
1st Value:

2nd Value: Value Percent:

Value Percent: 5.000 Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 1.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 8.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3