Manhole Inspection Report



Date: 05/14/2018 Weather: Coding: RZMACP

MH#: M-604-102 Owner: NA Len. Surveyed: 7.5
P.O.#: Surveyor: Jen Costello Rim to Invert: 7.9

Customer: Cert. #: U-907-5518 Wall Material: Concrete

(reinforced)

Street: 72' West of Washington St. 157' Sou Project: Hobart, IN

City: Hobart, IN GPS Northing: 2902035.882

Location: GPS Easting: 2902035.882

Drain Area: Northwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2.00 2200 4.00 O&M Index: O&M Quick: O&M Rating: 3100 3.00 3.00 Structural Index: Structural Quick: Structural Rating: 2.33 3122 7.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-604-10)2				
	.0	MGP	General Photo	10	NA
- 11	0.	DB	Displaced Brick	21	S 3
- 11	2.4	IW	Infil Weeper	37	M 2
- 11	2.4	MGO	General Observation	50	NA
- 11	7.5	DSF	Deposits Settled Fine	73	M 2
Camera Direction					



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

MGP

Wednesday, May 3, 2023

Code:



Code: **DB**

Description: Displaced Brick

Distance (ft): .0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 3
Clock To: 6
1st Value:
2nd Value:

Value Percent:

Step: NO

Remarks:



Code: IW

Description: Infil Weeper

Distance (ft): 2.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3
Clock To: 4
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME

Wednesday, May 3, 2023 3



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 7.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023 4