## **Manhole Inspection Report**

Date:	04/29/2018	Weather:		Coding:	RZMACP
MH#:	M-605-029	Owner:	NA	Len. Surveyed:	3.9
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	4.7
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	Ash St. 304' South	of Cleveland Ave.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2903144.841	
Location:			GPS Easting:	2903144.841	
Drain Area:	West		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	No	
Cover Size:	22.5		Potential for Runoff:	None	
Comments:					
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	3.00	Structural Qu	ick: 3100	Structural Rating:	3.00
Overall Index:	2.50	Overall Quick	c <b>3121</b>	Overall Rating:	5.00

RedZone

	n Code	Observation	Video (sec)	Grade
1-605-029				
.0	MGO	General Observation	10	NA
.0	DB	Displaced Brick	21	S 3
1.8	MGO	General Observation	38	NA
3.6	DSF	Deposits Settled Fine	55	M 2
3.9	MGO	General Observation	67	NA
Camera Direction				




Code:	MGO
Description:	General Observation
	-
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH

\_\_\_\_



Code: Description:	DB Displaced Brick
Distance (ft):	.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO

Remarks:



Code:	MGO
Description:	General Observation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Stan:	1.8 0 0
Step:	NO
Remarks:	UNDERSIDE OF FRAME



Code: Description:	DSF Deposits Settled Fine
Distance (ft):	3.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Step:	NO
Remarks:	



Code:MGODescription:General Observation

Distance (ft):	3.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY