
## **Manhole Inspection Report**

Date:	04/29/2018	Weather:		Coding:	RZMACP
MH#:	M-605-038	Owner:	NA	Len. Surveyed:	
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	7.4
Customer:		Cert. #:	U-907-5518	Wall Material:	Brick
Street:	Intersection of Per	insylvania St. and	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2902484.374	
Location:			GPS Easting:	2902484.374	
Drain Area:	West		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size:	22.5		Potential for Runoff:	None	
Comments:					
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	5.00	Structural Qu	ick: 5100	Structural Rating:	5.00
Overall Index:	3.50	Overall Quick	· 5121	Overall Rating:	7.00

RedZone





Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:	В
Description:	Broken
	•
Distance (ft):	.0
Structural Grade:	5
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	DSF Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	6.1 0 2 12 12 5.000 NO



Code:	MGO
Description:	General Observation
Distance (ft):	6.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY