## **Manhole Inspection Report**



Date: 04/29/2018 Weather: Coding: RZMACP

 MH#:
 M-605-045
 Owner:
 NA
 Len. Surveyed:
 7.0

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 7.6

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: Washington St. 221' North of 2nd St. Project: Hobart, IN

City: Hobart, IN GPS Northing: 2902163.963

Location: GPS Easting: 2902163.963
Drain Area: West GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-605-04	<b>1</b> 5				
	0. 🗸	MGP	General Photo	10	NA
- 11	1.5	MGO	General Observation	26	NA
- 11	6.1	DSF	Deposits Settled Fine	48	M 2
- 11	7.0	MGO	General Observation	60	NA
- 11					
- 11					
- 11					
<u> </u>					
Camera Direction					
D D					
a e					
Ē					
- 111					
- 111					
<b>↓</b>					
- 111					
- 11					
- 11					

Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACCESS MH** 

MGP

Wednesday, May 3, 2023 2



MGO Code:

Description: **General Observation** 

Distance (ft): 1.5 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: **UNDERSIDE OF FRAME** 



Code: DSF

Description: **Deposits Settled Fine** 

Distance (ft): 6.1 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 12 Clock To: 12 1st Value:

2nd Value:

Value Percent: 10.000 NO

Remarks:

Step:

Code:

MGO

Description: **General Observation** 



Distance (ft): 7.0 Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: **END SURVEY** 

Wednesday, May 3, 2023 3