Manhole Inspection Report



Date: 05/01/2018 Weather: Coding: RZMACP

MH#:M-605-060Owner:NALen. Surveyed:6.9P.O.#:Surveyor:Jen CostelloRim to Invert:7.2Customer:Cert. #:U-907-5518Wall Material:Brick

Street: Lake Park Ave. 415' South of Clevela Project: Hobart, IN

City: Hobart, IN GPS Northing: 41.53512192

Location: GPS Easting: -87.25969696
Drain Area: West GPS Accuracy: Nearest Meter


Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2300	O&M Rating:	6.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2300	Overall Rating:	6.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
-605-060				
.0	MGP	General Photo	10	NA
1.2	RFB	Roots Fine Barrel	24	M 2
1.6	MGO	General Observation	38	NA
3.2	RFB	Roots Fine Barrel	54	M 2
6.9	DSF	Deposits Settled Fine	72	M 2



Description:	General Photo		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Step:	NO		
Remarks:	ACCESS MH		

MGP

Wednesday, May 3, 2023

Code:



Code: RFB


Description: Roots Fine Barrel

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 1.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: RFB

Description: Roots Fine Barrel

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

4

Clock To:

1st Value:

2nd Value:

Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 6.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value:

2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023