Manhole In	spection Repor	t			RedZon
Date:	04/27/2018	Weather:		Coding:	RZMACP
MH#:	M-606-007	Owner:	NA	Len. Surveyed	8.0
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	9.7
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	Intersection of 8th	St. and Lake Park	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2904528.04	
Location:			GPS Easting:	2904528.04	
Drain Area:	Southeast		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	4.00	O&M Quick:	4100	O&M Rating:	4.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	4.00	Overall Quick	c 4100	Overall Rating:	4.00

Position	Code	Observation	Video (sec)	Grade
M-606-007				
.0	MGO	General Observation	10	NA
2.2	MGO	General Observation	28	NA
2.2	MGO	General Observation	42	NA
6.9	OBP	Obstacle External Pipe or Cable	63	M 4
8.0	MGO	General Observation	76	NA
Camera Direction				



Code: Description:	MGO General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	ACCESS MH



Code:	MGO
Description:	General Observation
Distance (ft):	2.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	UNDERSIDE OF FRAME



Code:	MGO
Description:	General Observation
Distance (ft):	2.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	MISSING STEP



Code: Description:	OBP Obstacle External Pipe or Cable
Distance (ft):	6.9
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	12
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	30.000
Step:	NO
Remarks:	



Code: Description: MGO General Observation

Distance (ft)	
Distance (ft):	8.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY

Wednesday, May 3, 2023