Manhole Inspection Report



Date:

04/27/2018

Weather:

Coding:

RZMACP

MH#:

M-606-009

Owner: NA Len. Surveyed:

13.5 Rim to Invert: 14.7

P.O.#: Customer: Surveyor: Cert. #:

Jen Costello U-907-5518

Wall Material:

Concrete (reinforced)

Street: City:

Intersection of 8th St. and 8th Pl.

Project:

Hobart, IN

Hobart, IN

GPS Northing:

2903960.58

None

Location: Drain Area:

Southwest

GPS Easting:

2903960.58

Cover Shape: Cover Size:

Circular

22.5

GPS Accuracy: Sub-Meter Evidence of Surcharge: No

Potential for Runoff:

Comments:

2.00

O&M Quick:

2100 3100

3121

O&M Rating:

2.00

3.00

5.00

O&M Index: Structural Index: Overall Index:

3.00 Structural Quick: 2.50 Overall Quick:

Structural Rating: Overall Rating:

Wednesday, May 3, 2023

1

	Position	Code	Observation	Video (sec)	Grade
M-606-00)9				
\mathcal{L}	0. //	MGO	General Observation	10	NA
- 11	\.0	DB	Displaced Brick	21	S 3
	1.6	MGP	General Photo	38	NA
- 11	5.4	IW	Infil Weeper	60	M 2
- 11	13.5	MGO	General Observation	87	NA
Camera Direction					



Code: MGO

Description: General Observation

Step: NO

Remarks: ACCESSM H



Code: **DB**

Description: Displaced Brick

Distance (ft): .0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 9
Clock To: 3
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Code: MGP

Description: General Photo

Distance (ft): 1.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 5.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 3

Clock To: 9

1st Value: 2

2nd Value: Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 13.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023