Manhole Ins	spection Repor	t			RedZo
Date:	04/27/2018	Weather:		Coding:	RZMACP
MH#:	M-606-021	Owner:	NA	Len. Surveyed:	16.0
P.O.#:		Surveyor:	Jen Costello	Rim to Invert:	17.2
Customer:		Cert. #:	U-907-5518	Wall Material:	Concrete (reinforced)
Street:	8th St. 247' West o	f 8th Pl.	Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	2903713.671	
Location:			GPS Easting:	2903713.671	
Drain Area:	Southwest		GPS Accuracy:	Sub-Meter	
Cover Shape:	Circular		Evidence of Surcharge:	Νο	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	4.00	Structural Qu	uick: 4100	Structural Rating:	4.00
Overall Index:	3.00	Overall Quic		Overall Rating:	6.00

P	osition	Code	Observation	Video (sec)	Grade
-606-021					
.0		MGO	General Observation	10	NA
.0	1	FM	Fracture Multiple	21	S 4
2.	4	MGP	General Photo	40	NA
11	1.1	IW	Infil Weeper	71	M 2
16	5.0	MGO	General Observation	92	NA



MGO General Observation
.0
0
0
NO
ACCESS MH



Code:	FM
Description:	Fracture Multiple
Distance (ft):	.0
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	12
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description:	MGP General Photo
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	2.4 0 0 VNO UNDERSIDE OF FRAME
	UNDERSIDE OF FRAME



Code: Description:	IW Infil Weeper
Distance (ft):	11.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: Description: MGO General Observation

Distance (ft):	16.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	END SURVEY