## **Manhole Inspection Report**



Date: 04/25/2018 Weather: Coding: RZMACP

MH#: M-606-023.1 Owner: NA Len. Surveyed: 6.2 P.O.#: Surveyor: Jen Costello Rim to Invert: 5.2 Customer: 8.7 Cert. #: U-907-5518 Wall Material: **Brick** 

Street: Ash St. 89' North of 8th Pl. Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0
Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
1-606-023.1				
.0	MGO	General Observation	10	NA
2.4	MGP	General Photo	28	NA
3.7	IW	Infil Weeper	44	M 2
6.2	MGO	General Observation	60	NA
Camera Direction				



Description:

Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Step:

General Observation

0

Clock Start/From:
0


NO

MGO

Remarks: ACCESS MH

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW


Description: Infil Weeper

Distance (ft): 3.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 2
1st Value:
2nd Value:

Step: NO

Remarks:

Value Percent:



Description: General Observation



Distance (ft): 6.2

Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023