Manhole Inspection Report



Date:

04/26/2018

Weather:

Cert. #:

Coding:

RZMACP

(reinforced)

MH#:

M-606-080

Owner: NA Len. Surveyed: 10.4

P.O.#:

Surveyor:

Rim to Invert:

10.4 Concrete Wall Material:

Customer:

160' South of Lake Shore Dr. East of Project:

Hobart, IN

Street: City:

Hobart, IN

GPS Northing:

2902556.637

Location:

GPS Easting:

2902556.637

Drain Area:

GPS Accuracy:

Jen Costello U-907-5518

Sub-Meter

Cover Shape: Cover Size:

Southwest Circular

22.5

Evidence of Surcharge: No

Comments:

Potential for Runoff:

None

O&M Index: Structural Index:

Overall Index:

2.00 0.00

2.00

O&M Quick: Structural Quick:

Overall Quick:

2100 0000 2100

O&M Rating: Structural Rating:

Overall Rating:

2.00 0.00 2.00

Wednesday, May 3, 2023

1

	Code	Observation	Video (sec)	Grade
606-080				
.0	MGO	General Observation	10	NA
.8	DAZ	Deposits Attached Other	23	M 2
1.7	MGO	General Observation	38	NA
3.0	IS	Infil Stain	54	NA
10.4	MGO	General Observation	81	NA



Code: MGO

Description: General Observation

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Step: NO

Remarks: ACCESS MH



Code: DAZ

Description: Deposits Attached Other

Distance (ft): .8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Step: YES
Remarks: GRASS



Code: MGO

Description: General Observation

Distance (ft): 1.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IS

Description: Infil Stain

Distance (ft): 3.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:
Value Percent:

Step: YES

Remarks:

Wednesday, May 3, 2023 3



Code: MGO

Description: General Observation

Distance (ft): 10.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY