Manhole Inspection Report



Date:

09/24/2022

Weather:

Coding:

RZMACP

MH#:

M-607-008

Owner: NA Len. Surveyed: 11.4

P.O.#:

Surveyor: Jen Costello U-907-5518 Cert. #:

Rim to Invert: Wall Material:

Concrete (cast in

6.00 4.00

10.00

place)

13.0

Street:

Customer:

West of Polly Ln. 109' South of Laur Project:

Hobart, IN

City:

Hobart, IN

GPS Northing:

2284118.984

Location:

Local Rural Streets

GPS Easting: 2904306.577

Drain Area: Cover Shape: Southwest

GPS Accuracy: Sub-Meter

Cover Size:

Circular

24.0

Evidence of Surcharge: Yes

Comments:

Potential for Runoff:

None

O&M Index:
Structural Index:

Overall Index:

2.00	O&M Quick:
2.00	Structural Quick:
2.00	Overall Quick:

2300	O&M Rating:
3111	Structural Rating
3123	Overall Rating:

13 3	_	on Code	Observation	Video (sec)	Grade
.0 SRI Surface Roughness Increased 21 2.5 MGO General Observation 40 8.6 IW Infil Weeper 66 10.2 DAR Deposits Attached Ragging 81 11.4 DSF Deposits Settled Fine 95 11.4 SAV Surface Aggregate Visible 106 11.4 MGO General Observation 117	507-008				
2.5 MGO General Observation 40 8.6 IW Infil Weeper 66 10.2 DAR Deposits Attached Ragging 81 11.4 DSF Deposits Settled Fine 95 11.4 SAV Surface Aggregate Visible 106 11.4 MGO General Observation 117	<u></u>	MGO	General Observation	10	NA
8.6 IW Infil Weeper 66 10.2 DAR Deposits Attached Ragging 81 11.4 DSF Deposits Settled Fine 95 11.4 SAV Surface Aggregate Visible 106 11.4 MGO General Observation 117	0.	SRI	Surface Roughness Increased	21	S 1
10.2 DAR Deposits Attached Ragging 81 11.4 DSF Deposits Settled Fine 95 11.4 SAV Surface Aggregate Visible 106 11.4 MGO General Observation 117	2.5	MGO	General Observation	40	NA
11.4 DSF Deposits Settled Fine 95 11.4 SAV Surface Aggregate Visible 106 11.4 MGO General Observation 117	8.6	IW	Infil Weeper	66	M 2
11.4 SAV Surface Aggregate Visible 106	10.2	DAR	Deposits Attached Ragging	81	M 2
	11.4	DSF	Deposits Settled Fine	95	M 2
11.4 MGO General Observation 117	11.4	SAV	Surface Aggregate Visible	106	S 3
	11.4	MGO	General Observation	117	NA

Code:

Remarks:



Description:	General Observation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO

access mh

MGO



Code: SRI

Description: Surface Roughness Increased

Distance (ft): .0
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: IW

Description: Infil Weeper

Distance (ft): 8.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: DAR

Description: Deposits Attached Ragging

Distance (ft): 10.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Step: YES

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 11.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To: 12

1st Value:

Value Percent: 5.000 Step: NO

Remarks:

2nd Value:



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): 11.4
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 3
Clock To: 9
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 11.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end of survey