Manhole Inspection Report



Date:

04/25/2018

Weather:

Cert. #:

NA

Coding: **RZMACP**

MH#:

M-607-014

Owner:

Len. Surveyed: 13.3

P.O.#:

8.7

John Kuglmaier Surveyor:

Rim to Invert: Wall Material:

14.0

Concrete (reinforced)

Street:

10th St. and Lake Park Ave. West Ce Project:

Hobart, IN

City:

Customer:

GPS Northing:

Location:

GPS Easting:

0.0 0.0

Drain Area:

0000

0000

Cover Shape:

Southwest

GPS Accuracy:

Potential for Runoff:

U-1215-07002349

Nearest Meter

Cover Size:

Circular

22.5

Hobart, IN

Evidence of Surcharge:

Yes None

Comments:

O&M Index:

0.00 O&M Quick:

0000 O&M Rating: 0.00 0.00

0.00

Structural Index: Overall Index:

0.00 Structural Quick: 0.00 Overall Quick:

Structural Rating: Overall Rating:

Wednesday, May 3, 2023

1

Position	Code	Observation	Video (sec)	Grade
07-014				
.0	MGP	General Photo	10	NA
2.5	MGP	General Photo	29	NA
/10.9	IS	Infil Stain	59	NA
10.9	IS	Infil Stain	71	NA
/ 10.9	IS	Infil Stain	82	NA
11.8	MGO	General Observation	96	NA



Description:	General Photo	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 10.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock Start/Fro
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 10.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11
Clock To: 1
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023 3



Code: IS

Description: Infil Stain

Distance (ft): 10.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 4

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 11.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.