Date:	04/06/2018	Weather:		Coding:	RZMACP
MH#:	M-607-029	Owner:	NA	Len. Surveyed:	6.7
P.O.#:		Surveyor:	John Kuglmaier	Rim to Invert:	7.1
Customer:		Cert. #:	U-1215-07002349	Wall Material:	Concrete (reinforced)
Street:	Laura Ln. 180' West of Lake Park Av		Project:	Hobart, IN	
City:	Hobart, IN		GPS Northing:	0.0	
Location:			GPS Easting:	0.0	
Drain Area:	Southwest Circular		GPS Accuracy:	Nearest Meter	
Cover Shape:			Evidence of Surcharge:	No	
Cover Size: Comments:	22.5		Potential for Runoff:	None	
O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	ick: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick	c: 2100	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
M-607-029	Ð				
\checkmark	.0	MGP	General Photo	10	NA
	2.2	MGP	General Photo	28	NA
	3.5	DSF	Deposits Settled Fine	45	M 2
	5.5	MGO	General Observation	60	NA
Camera Direction					



Code:	MGP
Description:	General Photo
	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	



Code: MGP Description: **General Photo** Distance (ft): 2.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks:



Code: Description:	DSF Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: Remarks:	3.5 0 2 12 12 5.000 NO



Code:	MGO
Description:	General Observation
//	
Distance (ft):	5.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	Ins. Comp.