## **Manhole Inspection Report**



Date: 04/25/2018 Weather: Coding: RZMACP

 MH#:
 M-607-054
 Owner:
 NA
 Len. Surveyed:
 9.8

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 9.9

Customer: 8.7 Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: West of Medlee Dr. 363' South of 10 Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0

Location: GPS Easting: **0.0** 

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-607-054				
.0	MGP	General Photo	10	NA
1.6	IS	Infil Stain	25	NA
/2.9	MGP	General Photo	41	NA
8.7	MGO	General Observation	67	NA
Camera Direction				



Description:	<b>General Photo</b>
Distance (ft): Structural Grade: O&M Grade: Clock Start/From:	.0 0 0
Clock To: 1st Value: 2nd Value:	
Value Percent: Step: Remarks:	NO

MGP

Wednesday, May 3, 2023

Code:



Code: IS

Description: Infil Stain

Distance (ft): 1.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 12

Clock To: 12

1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGP

Description: General Photo

Distance (ft): 2.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

Step: NO

Remarks:

2nd Value: Value Percent:



Code: MGO

Description: General Observation

Distance (ft): 8.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

3