Manhole Inspection Report



04/05/2018 Date: Weather: Coding: MH#: M-607-075 Owner: NA Len. Surveyed: 11.9

P.O.#: Surveyor: John Kuglmaier Rim to Invert: Customer: U-1215-07002349 Wall Material: Concrete Cert. #:

(reinforced)

RZMACP

West 61st St. and 14th St. Hobart, IN Street: Project:

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest **GPS Accuracy: Nearest Meter**

Cover Shape: Circular Evidence of Surcharge: No Potential for Runoff: Cover Size: 22.5 None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

1 Wednesday, May 3, 2023

	Code	Observation	Video (sec)	Grade
1-607-075				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
/5.2	IS	Infil Stain	48	NA
8.5	DAZ	Deposits Attached Other	66	M 2
9.8	MGO	General Observation	80	NA
Camera Direction				



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023

Code:



Code: MGP


Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 5.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 5

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 8.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks: Mixed materials

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 9.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4

Wednesday, May 3, 2023