Manhole Inspection Report



Date: 04/08/2018 Weather: Coding: RZMACP

 MH#:
 M-608-017
 Owner:
 NA
 Len. Surveyed:
 4.4

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 5.2

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 354' North of 61st Ave. 448' East of Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: Southwest GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	2.00	O&M Quick:	2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	2100	Overall Rating:	2.00

Wednesday, May 3, 2023

Positio	on Code	Observation	Video (sec)	Grade
M-608-017				
.0	MGP	General Photo	10	NA
1.9	DAZ	Deposits Attached Other	26	M 2
2.1	MGP	General Photo	40	NA
3.7	MGO	General Observation	57	NA
Camera Direction				



Code:	MGP
Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

Wednesday, May 3, 2023



Code: DAZ


Description: Deposits Attached Other

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: 10.000
Step: NO

Remarks: Mixed materials



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 3.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3