Manhole Inspection Report



Date: 04/08/2018 Weather: Coding: RZMACP

MH#: M-608-025 Owner: NA Len. Surveyed: 5.8
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 6.6

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 272' South of 14th St. 483' East of W Project: Hobart, IN

City: Hobart, IN GPS Northing: 2903848.729

Location: GPS Easting: 2903848.729

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2.00 2200 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2200 4.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

Posi	tion Code	Observation	Video (sec)	Grade
-608-025				
.0	MGP	General Photo	10	NA
2.1	MGP	General Photo	28	NA
3.7	OBB	Obstacle Brick	45	M 2
3.7	OBB	Obstacle Brick	56	M 2
4.8	MGO	General Observation	70	NA
,				
ш				




Description:	General Photo
Distance (ft):	.0
Structural Grade: O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2

Code:



Code: MGP

Description: General Photo

Distance (ft): 2.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: OBB

Description: Obstacle Brick

Distance (ft): 3.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To:

1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Code: OBB

Description: Obstacle Brick



Distance (ft): 3.7
Structural Grade: 0

O&M Grade: 2
Clock Start/From: 2

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Step: NO

Remarks:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 4.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

4

Wednesday, May 3, 2023