## **Manhole Inspection Report**



Date: 04/08/2018 Weather: Coding: RZMACP

MH#: M-608-030 Owner: NA Len. Surveyed: 4.8
P.O.#: Surveyor: John Kuglmaier Rim to Invert: 5.3

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: 238' South of 14th St. 665' West of Project: Hobart, IN

 City:
 Hobart, IN
 GPS Northing:
 2904000.115

 Location:
 GPS Easting:
 2904000.115

Drain Area: Southwest GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-608-03	30				
	0	MGP	General Photo	10	NA
- 11	1.8	MGP	General Photo	28	NA
- 11	2.0	DAZ	Deposits Attached Other	42	M 2
- 11	3.9	MGO	General Observation	57	NA
Camera Direction					

Code:



Description:	<b>General Photo</b>	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Step:	NO	
Remarks:		

MGP

Wednesday, May 3, 2023



Code: MGP

Description: General Photo

Distance (ft): 1.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:
Value Percent: 5.000
Step: NO

Remarks: Mixed materials



Code: MGO

Description: General Observation

Distance (ft): 3.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023 3