Manhole Inspection Report



Date: 03/29/2018 Weather: Coding: RZMACP

 MH#:
 M-703-023
 Owner:
 NA
 Len. Surveyed:
 6.1

 P.O.#:
 Surveyor:
 John Kuglmaier
 Rim to Invert:
 7.1

Customer: Cert. #: U-1215-07002349 Wall Material: Concrete

(reinforced)

Street: North Pheasant Run Dr. 371' North Project: Hobart, IN

City: Hobart, IN GPS Northing: 0.0 Location: GPS Easting: 0.0

Drain Area: North GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: 23.0 Potential for Runoff: None


Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

Pos	ition Code	Observation	Video (sec)	Grade
M-703-023				
.0	MGP	General Photo	10	NA
2.0	MGP	General Photo	28	NA
5.4	MGO	General Observation	48	NA
Camera Direction				


Code:



Description:	General Photo
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Step:	NO
Remarks:	

MGP

Wednesday, May 3, 2023 2



Code: MGP

Description: General Photo

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 5.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: Ins. Comp.

Wednesday, May 3, 2023