Manhole Inspection Report



Date:

05/16/2018

Weather:

NA

Coding:

RZMACP

MH#:

M-704-006

Owner: I

Len.

Len. Surveyed: **14.2** Rim to Invert: **15.1**

P.O.#: Customer: Surveyor: Cert. #: Jen Costello U-907-5518

Wall Material:

Concrete (reinforced)

Street:

Linda St. 303' South of East Hickey S Project:

Hobart, IN

City:

Hobart, IN

GPS Northing:

2907098.035

Location:

GPS Easting:

2907098.035

Drain Area:

Northeast

GPS Accuracy:

Sub-Meter

Cover Shape:

Circular

Evidence of Surcharge: No

Cover Size: 2

22.5

Potential for Runoff: None

Comments:

O&M Index:

2.00 0.00 __O&M Quick:

2100 0000

O&M Rating: Structural Rating: 2.00 0.00

2.00

Structural Index:
Overall Index:

0.00Structural Quick:2.00Overall Quick:

Quick: 2100 Overall Rating:

Wednesday, May 3, 2023

Position	Code	Observation	Video (sec)	Grade
M-704-006				
.0	MGP	General Photo	10	NA
2.0	MGO	General Observation	27	NA
11.1	OBB	Obstacle Brick	59	M 2
14.2	MGO	General Observation	76	NA
Camera Direction				


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: access mh

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: underside of frame



Code: OBB

Description: Obstacle Brick

Distance (ft): 11.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Step: YES

Remarks:

Code: MGO

Description: General Observation



Distance (ft): 14.2 Structural Grade: 0

O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: end survey

Wednesday, May 3, 2023 3