## **Manhole Inspection Report**



Date: 05/03/2018 Weather: Coding: RZMACP

M-704-009 MH#: Owner: NA Len. Surveyed: 18.7 P.O.#: Surveyor: Jen Costello Rim to Invert: 20.5 U-907-5518 Wall Material: **Brick** Customer: Cert. #:

Street: Intersection of Cleveland Ave. and Project: Hobart, IN

City: Hobart, IN GPS Northing: 2906523.76


Location: GPS Easting: 2906523.76
Drain Area: Northeast GPS Accuracy: Sub-Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

2100 2.00 2.00 O&M Index: O&M Quick: O&M Rating: 54.00 3.00 3B00 Structural Quick: Structural Index: Structural Rating: 3B21 56.00 Overall Index: 2.95 Overall Quick: Overall Rating:

Wednesday, May 3, 2023




Code: MGO
Description: General Observation

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks: ACCESS MH



Code: SAV


Description: Surface Aggregate Visible

Distance (ft): 1.0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value: Value Percent:

Step: NO

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 2.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: IW

Description: Infil Weeper

Distance (ft): 18.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 8
1st Value: 2
2nd Value:

Step: NO

Remarks:

Value Percent:

Wednesday, May 3, 2023



Code: MGO

Description: General Observation

Distance (ft): 18.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY



Code: SAV

Description: Surface Aggregate Visible

Distance (ft): 18.7
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:
Value Percent:

Step: NO

Remarks:

Wednesday, May 3, 2023