Manhole Inspection Report



Date: 04/29/2018 Weather: Coding: RZMACP

 MH#:
 M-704-014
 Owner:
 NA
 Len. Surveyed:
 10.5

 P.O.#:
 Surveyor:
 Jen Costello
 Rim to Invert:
 11.0

 Customer:
 Cert. #:
 U-907-5518
 Wall Material:
 Brick

Street: Intersection of Michigan Ave. and H Project: Hobart, IN

City: Hobart, IN GPS Northing: 41.53805161
Location: GPS Easting: -87.25195312

Drain Area: Northeast GPS Accuracy: Nearest Meter

Cover Shape: Circular Evidence of Surcharge: No
Cover Size: Potential for Runoff: None

Comments:

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Wednesday, May 3, 2023

	Position	Code	Observation	Video (sec)	Grade
M-704-01	. 4				
	0	MGO	General Observation	10	NA
- 11	1.4	MMC	Material Change	24	NA
	1.4	MGO	General Observation	37	NA
	10.5	MGO	General Observation	69	NA
Camera Direction					
Ш					



General Observation Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACCESS MH**

MGO

Wednesday, May 3, 2023 2

Code:



Code: MMC


Description: Material Change

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO Remarks: BRICK



Code: MGO

Description: General Observation

Distance (ft): 1.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 10.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/Pro Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023