Manhole Inspection Report



Date:

05/16/2018

Weather:

Coding:

RZMACP

MH#:

M-704-059

Owner: NA Len. Surveyed:

P.O.#:

Surveyor: Jen Costello U-907-5518 Cert. #:

Rim to Invert:

4.7 Concrete Wall Material:

(reinforced)

4.2

Street:

Customer:

East of Lake Park Ave. 388'. North of Project:

Hobart, IN

City:

Hobart, IN **GPS Northing:** 2904832.021

Location:

GPS Easting:

2904832.021

Drain Area: Cover Shape: North Circular GPS Accuracy: **Sub-Meter**

No

Cover Size:

22.5

Evidence of Surcharge:

Potential for Runoff: None

Comments:

0.00 O&M Quick: 0.00

0000 O&M Rating: 0000 Structural Rating: 0000

Overall Rating:


0.00 0.00

0.00

O&M Index: Structural Index: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
M-704-059					
	0	MGP	General Photo	10	NA
- 11	1.3	MGO	General Observation	26	NA
- 11	4.2	MGO	General Observation	45	NA
Camera Direction					


Code:



Description: **General Photo** Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Step: NO Remarks: **ACCESS MH**

MGP

Wednesday, May 3, 2023 2



Code: MGO

Description: General Observation

Distance (ft): 1.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: UNDERSIDE OF FRAME



Code: MGO

Description: General Observation

Distance (ft): 4.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Step: NO

Remarks: END SURVEY

Wednesday, May 3, 2023 3